



How-To Guide:

Recovering the factory's
Yamaha Drive model seat cushion



Written by



Step 1 (Optional)

- Carefully slit existing vinyl upholstery away from plastic base using a sharp utility knife. Do this around the entire perimeter of the seat.




Step 2 (Optional)



- Slowly peel existing vinyl upholstery from foam substrate, leaving as much of foam substrate intact.
- HINT – If available, first use an industrial heat gun to soften the adhesive bond between the vinyl cover and foam.



Your seat should look like this



Discard original vinyl skin

Step 3



- Center new vinyl seat bottom cover manufactured by GR Golf over old foam, as shown.

Step 4



- On clean work surface, turn over cushion and staple through vinyl into plastic base.

I am having issues with the head of the staple going thru the vinyl, what can I do?

- Decrease air pressure (example: we have ours set to 80 lbs)
- Check driver - pull trigger on gun and hold in. how far is driver sticking out? you may benefit from shortening it – tap on a grinder

Step 5

- Using utility knife, neatly trim excess vinyl along staple line.



Your finished Yamaha Drive seat should look like this

- Bottom side view at left
- Top side view below

